

## TABLE OF CONTENTS

---

<b><u>Section</u></b>	<b><u>Page</u></b>
<b>1.0 Introduction</b>	<b>1-1</b>
1.1 Purpose of Report	1-1
1.2 Site Background	1-3
1.2.1 Site Description	1-3
1.2.2 Site History	1-3
1.2.3 Previous Investigations	1-5
1.3 Report Organization	1-10
<b>2.0 Study Area Investigation</b>	<b>2-1</b>
2.1 Surface Features	2-1
2.2 Contaminant Source Investigations	2-1
2.3 Surface Water and Sediment Investigations	2-5
2.4 Geological Investigations	2-5
2.4.1 Subsurface Soil Investigations	2-7
2.4.2 Bedrock Investigations	2-8
2.5 Groundwater Investigations	2-9
2.5.1 Residential Drinking Water Wells	2-9
2.5.2 Temporary Monitoring Wells	2-10
2.5.3 Permanent Groundwater Monitoring Wells	2-12
2.6 Decontamination Procedures	2-17
2.7 Quality Assurance/Quality Control	2-17
2.8 Demographics, Land and Water Use	2-18
2.9 Ecological Survey	2-18
<b>3.0 Physical Characteristics</b>	<b>3-1</b>
3.1 Surface Features	3-1
3.2 Meteorology	3-3
3.3 Surface Water Hydrology	3-4
3.4 Geology	3-4
3.5 Hydrogeology	3-6
3.5.1 Geophysical Borehole Logging	3-16
3.6 Residential Well Inventory and Water Use	3-18
3.7 Ecology	3-18
3.7.1 Wildlife and Natural Resources	3-18
3.7.2 Bioassessment	3-18

## TABLE OF CONTENTS (continued)

---

<u>Section</u>	<u>Page</u>
<b>4.0 Nature and Extent of Contamination</b>	<b>4-1</b>
4.1 Surface Water and Sediments	4-1
4.2 Subsurface Soils	4-2
4.3 Groundwater	4-3
4.3.1 Groundwater Plume in 1991	4-3
4.3.2 March/April 1996 Groundwater Plume	4-8
4.3.3 Shallow Groundwater Plume	4-8
4.3.4 Top of Bedrock Groundwater Plume	4-13
4.3.5 Bedrock Groundwater Plume	4-19
4.3.6 Other Constituents	4-20
4.4 Quality Assurance and Quality Control	4-22
<b>5.0 Contaminant Fate and Transport</b>	<b>5-1</b>
5.1 Potential Routes of Migration	5-1
5.2 Contaminant Persistence	5-1
5.2.1 Chemical Properties of Contaminants	5-1
5.2.2 Site-Specific Chemical Properties	5-2
5.2.3 Contaminant Transport - Groundwater	5-3
5.2.4 Contaminant Transport - Surface Water	5-6
5.2.5 Degradation Mechanisms in the Natural Environment	5-7
5.3 Site-Specific Fate and Transport	5-9
5.3.1 Introduction and Objective	5-9
5.3.2 Background	5-9
5.3.3 Field Activities and Results	5-9
5.3.4 Transport Modeling Calculations	5-11
5.3.5 Sensitivity Analysis	5-15
<b>6.0 Conclusions and Recommendations</b>	<b>6-1</b>
6.1 Conclusions	6-1
6.2 Recommendations	6-2
<b>7.0 References</b>	<b>7-1</b>

Appendix A - Field Investigation Data

Appendix B - Analytical Data

Appendix C - Acronyms/Abbreviations

## LIST OF FIGURES

---

<b><u>Figure</u></b>	<b><u>Page</u></b>
1-1 Site Location Map	1-2
1-2 RI/FS Study Area	1-4
1-3 Approximate PCE/TCE Groundwater Plume, 1991	1-6
1-4 NCDEHNR Soil Sample Locations, July 1993	1-7
1-5 SESD Mar/Apr 1996 Sample Locations	1-8
2-1 June/July 1996 Subsurface Soil Boring Locations	2-2
2-2 June 1996 Shallow Temporary Well Locations	2-3
2-3 Top of Bedrock Temporary Wells & Permanent Monitoring Well Locations	2-4
2-4 June 1996 Surface Water/Sediment Sample Location	2-6
2-5 Bioassessment Sites, Unnamed Tributary - A	2-20
2-6 Reference Site, Dutchmans Creek	2-21
3-1 Topographic Map	3-2
3-2 Surface Water Pathway	3-5
3-3 Cross-Section Base Map, August 1996	3-7
3-4 Geologic Cross-Section A-A', Aug 1996	3-8
3-5 Geologic Cross-Section B-B', Aug 1996	3-9
3-6 Geologic Cross-Section C-C', Aug 1996	3-10
3-7 Top of Bedrock Contours, August 1996	3-11
3-8 Saprolite Aquifer, Potentiometric Map, Oct 1996	3-14
3-9 Oct 1996 Bedrock Aquifer, Potentiometric Map	3-15
3-10 Oct 1996 Residential Well Survey Results	3-19
3-11 Location of Rankin Hardwood Forest	3-20
4-1 PCE Groundwater Contamination, 1991	4-5
4-2 TCE Groundwater Contamination, 1991	4-6
4-3 Cis-1,2-DCE Groundwater Contamination, 1991	4-7
4-4 Mar/Apr 1996 PCE Contaminant Plume	4-9
4-5 Shallow Groundwater Plume, PCE Contamination, June 1996	4-10
4-6 Shallow Groundwater Plume, TCE Contamination, June 1996	4-11
4-7 Shallow Groundwater Plume, DCE Contamination, June 1996	4-12

## **LIST OF FIGURES (continued)**

---

<b><u>Figure</u></b>	<b><u>Page</u></b>
4-8 Top of Bedrock Groundwater Plume, Temporary Wells PCE Contamination, July/August 1996	4-14
4-9 Top of Bedrock Groundwater Plume (Temporary Wells and Permanent Wells) PCE Contamination, October/ November 1996	4-16
4-10 Top of Bedrock Groundwater Plume (Temporary Wells and Permanent Wells) TCE Contamination, October/ November 1996	4-17
4-11 Top of Bedrock Groundwater Plume (Temporary Wells and Permanent Wells) Cis-1,2-DCE Contamination October/November 1996	4-18
4-12 Bedrock Groundwater Plume (Bedrock MW and Potable Wells) PCE Contamination, Oct/Nov 1996	4-20
4-13 Bedrock Groundwater Plume (Bedrock MW and Potable Wells) TCE Contamination, Oct/Nov 1996	4-21
4-14 Bedrock Groundwater Plume (Bedrock MW and Potable Wells) Cis-1,2-DCE Contamination, Oct/Nov 1996	4-22
4-15 1,1 Dichloroethene Contamination in Top of Bedrock Aquifer, Oct/Nov 1996	4-23
4-16 1,1 Dichloroethene Contamination in Bedrock Aquifer, Oct/Nov 1996	4-24
4-17 Trichlorofluoromethane Contamination in Bedrock Aquifer, Oct/Nov 1996	4-25

## LIST OF TABLES

---

<b><u>Table</u></b>	<b><u>Page</u></b>
1-1 March 1996 Private Well Sampling VOA Results	1-9
1-2 April 1996 Private Well Sampling	1-9
2-1 Contaminant Source Area Investigations	2-1
2-2 Surface Water and Sediment Sample Locations	2-5
2-3 Subsurface Soil Sampling	2-7
2-4 Geophysical Borehole Logging Tools	2-9
2-5 Residential Drinking Water Wells	2-11
2-6 Location and Purpose of Monitor Wells	2-13
2-7 Specifications for Top-of-Bedrock Monitor Wells	2-14
2-8 Specifications for Bedrock Monitor Wells	2-14
2-9 Well Stabilization Criteria	2-16
2-10 Quality Control/Quality Assurance Samples Collected	2-18
3-1 Climatological Data for Charlotte, North Carolina	3-3
3-2 Top of Bedrock Elevations	3-12
3-3 1996 Groundwater Elevations	3-13
3-4 Geophysical Borehole Logging Zones of Interest in Monitor Wells	3-22
3-5 Results of In-Situ Physicochemical Measurements; Unnamed Tributary A (UT) Adjacent to the Site and Dutchmans Creek (DC) Reference Stream; July 1996	
4-1 Main Contaminants in the Surface Water/Sediment	4-1
4-2 Main Contaminants at 5 Foot Zone of Subsurface Soils	4-2
4-3 Main Contaminants at 10 Foot Zone of Subsurface Soils	4-2
4-4 Main Contaminants at 15 Foot Zone of Subsurface Soils	4-3
4-5 Main Contaminants at 20 Foot Zone of Subsurface Soils	4-3
4-6 Main Contaminants in the Goundwater in 1991	4-4
4-7 Main Contaminants in the GW in March/April 1996	4-8
4-8 Main Contaminants in the Shallow GW Plume in June 1996	4-13
4-9 Main Contaminants in Temporary TOB GW Plume July/Aug 1996	4-13

## LIST OF TABLES (continued)

---

<b><u>Table</u></b>	<b><u>Page</u></b>
4-10A Main Inorganic Contaminants in the Perm TOB GW Plume Oct 1996	4-15
4-10B Main Organic Contaminants in the Perm TOB GW Plume Oct 1996	4-15
4-11A Main Organic Contaminants in the Bedrock GW Plume, Permanent Monitoring Wells, Oct/Nov 1996	4-19
4-11B Main Inorganic Contaminants in the Bedrock GW Plume, Permanent Monitoring Wells, Oct/Nov 1996	4-20
4-12A Main Organic Contaminants in the GW Plume, Residential Drinking Water Wells, Mar thru Sept 1996	4-21
4-12B Main Inorganic Contaminants in the GW Plume, Residential Drinking Water Wells, Mar thru Sept 1996	4-22
4-13A Quality Assurance/Quality Control Samples	4-23
4-13B Quality Assurance/Quality Control Samples, VOC Samples, Mar/Nov 1996	4-24
4-13C Quality Assurance/Quality Control Samples, Inorganic Samples, Mar/Nov 1996	4-25
4-13D Quality Assurance/Quality Control Samples, BNA Samples, Mar/Nov 1996	4-26
5-1 Physical Properties of Organic Contaminants	5-4
5-2 Physical Properties of Organic Contaminants	5-5
5-3 Hydraulic Conductivities in the Saprolite	5-10
5-4 Hydraulic Conductivities in the Bedrock	5-10
5-5 Bioscreen Model Input Parameters	5-11
5-6 Estimated Contaminant Migration Distances for the Saprolite	5-13
5-7 Estimated Contaminant Migration Distances for the Bedrock	5-14
5-8 Sensitivity Analysis Results for the Site Modeling Effort	5-18

North Belmont PCE Site  
Remedial Investigation  
North Belmont, Gaston County, NC  
SESD Project No. 96S-058/June, 1997

## **Appendix B - Analytical Data**

The laboratory data is not available electronically for this study.  
If you need copies of the laboratory data sheets for this study, please contact:

**Archie Lee**  
**US-EPA, Region 4, SESD**  
**980 College Station Road**  
**Athens, GA 30605**  
**(706) 355-8623 or (706) 355-8500**  
E-mail: [lee.archie@epa.gov](mailto:lee.archie@epa.gov)